


EXPLOSIVE VIEW OF WD010120450



PART LIST OF WD010120450

NO	DESCRIPTION	Q'TY	NO	DESCRIPTION	Q'TY
1	Left head screw	1	13	Carbon brush	2
2	Chuck	1	14	Cap of carbon brush	2
3	Woodruff key	1	15	Right housing	1
4	Output spindle	1	16	Screw	10
5	Bearing	1	17	Stator	1
6	Bush	1	18	Left housing	1
7	Gear	1	19	Switch	1
8	Circlip	1	20	Wire	1
9	Bearing	1	21	Wire	1
10	Bearing	2	22	Cable protector	1
11	Rotor	1	23	Cable and plug	1
12	Brush holder	2			